**Bugfixes
2022-23.60**

Technical Inquiries

Please ask the responsible contact person in our support department.
E-mail: e3-support@de.zuken.com

Note:

Contact

Zuken E3 GmbH
Laemmerweg 55
D-89079 Ulm/Einsingen

Phone : +49 7305 9309-0
Fax:+49 7305 9309-99
Web: http://www.zuken.com
E-mail: e3-info@de.zuken.com

Bugfixes

The bug fixes are sorted and listed by designer number(s). This enables you, for example, to easily search for bugs reported to our support office.

Designer-20606	When saving connector with multiply used structure to database, query is missing asking the user whether to update all block components using this connector
Designer-42978	Empty structure nodes cannot be deleted (because of wrong assignments with connector with inserts)
Designer-43154	Inserting a component from a database assembly from the database onto a formboard sheet, the original view is placed
Designer-43182	When opening a multiuser project, pins are unexpectedly changed and sent to the multiuser server
Designer-43262	Digitizing dimension points from 2022-23.00, points of symbol graphics are found instead of line ends
Designer-43401	PDF export from project tree takes structure node attributes incorrectly
Designer-43453	Models are not displayed in 2D view in certain slots
Designer-43483	Symbol can be moved to connection, although a connection is not possible
Designer-43495	PDF export - hyperlink no longer works since patch 24.10.
Designer-43533	COM: Job.GetCurrentUserNames - When a singleuser project is open, E3 closes
Designer-43539	If DBE is opened from Multiuser, the autosave file is not saved correctly
Designer-43578	Unplaced formboard views are not deleted during "delete unused objects" (When they are part of an assembly)

Designer-43598	Behaviour of text type #7 (signal indicator) with the function 'Disconnect - delete signal' on a bus pin - signal indicator is still displayed
Designer-43605	The database conversion from E3.2021 to E3.2022/E3.2023 does not work if the DB is on Oracle
Designer-43630	Exporting multiuser projects or copying from existing Multiuser projects may export too many primary keys (with Oracle DB)
Designer-43633	Missing dimensions of arced line graphics when exporting the project to PDF
Designer-43661	Crash when opening older projects because of inconsistency
Designer-43684	PDF Export report Error: E - Error in function int __cdecl CPDFGraphic - if GIF files are included
Designer-43713	2 digits after decimal point for outer diameter via COM is output with many decimal places
Designer-43715	Error for 'Align object' with connector and mating connector symbols in context menu
Designer-43766	A dynamic mounting rail/dynamic cable duct cannot be created on a mounting plate.
Designer-43787	Different text order in properties
Designer-43821	COM: After executing 'SymbolInterface::AssignToConnector()', the project inconsistency 'E - CCID:001168: check_node(xxx (xxx)): PartSignalptr (xxx) 'xxx' exist, but Signalclass (xxx) '' is not correct.' appears
Designer-43822	Color table under Format in DBE does not show any tooltips
Designer-43830	Representation of the graphic line in the project does not correspond to the representation in the database
Designer-43859	Export and import of complete project does not work (if unplaced devices are exported as well)
Designer-43865	Different representation of internal/external destinations in terminal plan
Designer-43891	"Reconnect conductor" connects end pin 2 to itself
Designer-43935	Importing subcircuits into structure node, structure attributes are changed
Designer-43951	With COM, no active entry can be created at the top menu level
Designer-43972	If setting "Use signal equivalence" is active, wires routed inside the panel are displayed as external in the terminal plan
Designer-43978	Performance improvement when switching options if there are many formboard tables in the project [42122]
Designer-43992	Performance improvement when switching options if there are many formboard tables in the project [42122]

Additionally to the bug fixes we also have added some new / enhanced functionality in this patch

Designer-43599   COM: Job.ActivateOptionIds and Job.DeactivateOptionIds should also work if an option is locked in the project

Americas

North America
Zuken USA Inc.
Westford, MA 01886, USA
Tel: +1 978 692 4900

Asia

Japan
Zuken (World Wide Head Office)
Yokohama, Kanagawa 224-8585, Japan
Tel: +81 45 942 1511

China
Zuken (Shanghai) Technical Center Co., Ltd.
Room 301, No.555 Nanjing West Road, Shanghai,
200041, People's Republic of China
Tel: +86-21-3218-1784

Korea
Zuken Korea Inc.
Seoul 135-283, Korea
Tel: +82 2 5648031

Singapore
Zuken Singapore Pte Ltd.
#22-05 Gateway East, Singapore 189721
Tel: +65 6392 5855

Taiwan
Zuken Taiwan Inc.
Taipei 110, Taiwan
Tel: +886 2 7718 1116

Europe

Germany
Zuken GmbH (European HQ)
D-85399 Hallbergmoos, Germany
Tel: +49 89 7104059 00

Zuken E3 GmbH
D-89079 Ulm, Germany
Tel: +49 7305 9309 0

Zuken E3 GmbH
D-30659 Hannover, Germany
Tel: +49 511 8595 9489

Switzerland
Zuken E3 GmbH
CH-5504 Othmarsingen, Switzerland
Tel: +41 62 561 08 00

United Kingdom
Zuken UK Ltd.
Bristol, BS32 4RF, UK
Tel: +44 1454 207 801

France
Zuken S.A.
#91974 Les Ulis Cédex, France
Tel: +33 1 69 29 48 00

Italy
Zuken S.r.l.
20090 Milanofiori Assago, Milan, Italy
Tel: +39 02 575 921

Netherlands
Zuken GmbH
NL-6075 HA Herkenbosch, The Netherlands
Tel: +31 475 520 998

www.zuken.com/e3

ZUKEN®